Brief History

Significant Dates

Discontinued sluicing bottom ash to CCR units (i.e., ponds) at both JRPS/JTEC – prior to 10/19/2015

Certified intent to close ponds at both sites/closure by removal – 12/14/2015

Permitted (permit modification) to burn natural gas only at James River Power Station – 1/29/2016

Removed all wastewater, ash, liner materials at John Twitty Energy Center – prior to 9/30/2016

Certified closure verification/completed at John Twitty Energy Center – 11/25/2016 (updated 4/4/2017)

Annual Closure Progress Report completed and posted for both sites – 1/12/2017

Removed all wastewater, ash, liner materials at James River Power Station – prior to 6/30/2017

Certified closure verification/completed at James River Power Station – 8/8/2017

Aerial View JTEC Site



Aerial View JTEC ¥#-F2-130 w-PZ-090 N Site M#~54~34 98-PZ-080 99-P7-13 ¥#--72-000 W-34-4 K 6 **684-P**7-110 W-3-1 E #2460


JTEC Before



JTEC After



Aerial View JRPS Site






ED_002911D_00107461-00008

JRPS Before



JRPS After



JRPS After





1. Description

The JTEC site is owned and operated by City Utilities of Springfield, Missouri, and is located west of the city. The plant consists of dual-fueled (coal or natural gas) boilers. Originally, bottom ash was sluiced to two 7-9 acre on-site temporary holding ponds. The ash was stored in the ponds until an appreciable volume was reached. The ponds were drained and the ash excavated and placed within the on-site permitted landfill. Both ponds were originally constructed with a clay liner. After the last cleaning additional clay was placed in the east pond.

City Utilities decided to close the temporary holding ponds at John Twitty Energy Center (JTEC) by removing all of the coal combustion residuals (CCR) from the surface impoundments. This was accomplished in accordance with the construction drawings and specifications under PO 131771. The liners were also removed as a part of the excavation of the ponds.

The ponds were verified clean by the process described in the document titled "Clean Closure Verification of CCR Temporary Holding Ponds" which is located in the site Operating Record. The document describes the method of determining the complete removal of CCR within the ponds and the handling and testing performed to accomplish the verification.

This verification is for both the east and west temporary holding ponds (See Attachment A for a revised grid drawing showing samples locations for this verification).

The following table is a summary of the results from the testing. Test result data information can be seen in Attachment B.

| JTEC 1-C 0 JTEC 1-D 1 JTEC 2-B 6 JTEC 2-C 2 JTEC 2-D 0 JTEC 2-F 1 JTEC 2-E 3 JTEC 2-G 17 JTEC 2-H 0 JTEC 3-B 3 JTEC 3-D 4 JTEC 3-C 0 JTEC 3-F 4 JTEC 3-G 2 JTEC 3-J 2 JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 ITEC 4-H 2 | _SAMPLE_ID | RESULT |
|---|-----------------|--------|
| JTEC 2-B 6 JTEC 2-C 2 JTEC 2-D 0 JTEC 2-F 1 JTEC 2-E 3 JTEC 2-G 17 JTEC 3-B 3 JTEC 3-B 3 JTEC 3-D 4 JTEC 3-C 0 JTEC 3-F 4 JTEC 3-F 4 JTEC 3-B 2 JTEC 3-C 0 JTEC 3-F 4 JTEC 3-B 2 JTEC 3-C 0 JTEC 3-C 0 JTEC 3-C 0 JTEC 3-H 1 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 1-C | 0 |
| JTEC 2-C 2 JTEC 2-D 0 JTEC 2-F 1 JTEC 2-E 3 JTEC 2-G 17 JTEC 3-B 3 JTEC 3-B 3 JTEC 3-D 4 JTEC 3-C 0 JTEC 3-F 4 JTEC 3-F 4 JTEC 3-G 2 JTEC 3-H 1 JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 1-D | 1 |
| JTEC 2-D 0 JTEC 2-F 1 JTEC 2-B 3 JTEC 2-G 17 JTEC 2-H 0 JTEC 3-B 3 JTEC 3-D 4 JTEC 3-C 0 JTEC 3-F 4 JTEC 3-F 4 JTEC 3-B 2 JTEC 3-F 4 JTEC 3-F 1 JTEC 3-J 2 JTEC 3-H 1 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 2-B | 6 |
| JTEC 2-F 1 JTEC 2-E 3 JTEC 2-G 17 JTEC 2-H 0 JTEC 3-B 3 JTEC 3-D 4 JTEC 3-C 0 JTEC 3-F 4 JTEC 3-F 0 JTEC 3-B 2 JTEC 3-F 1 JTEC 3-G 2 JTEC 3-H 1 JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 2-C | 2 |
| JTEC 2-E 3 JTEC 2-G 17 JTEC 2-H 0 JTEC 3-B 3 JTEC 3-D 4 JTEC 3-C 0 JTEC 3-F 4 JTEC 3-F 0 JTEC 3-B 0 JTEC 3-C 0 JTEC 3-F 4 JTEC 3-B 2 JTEC 3-C 0 JTEC 3-C 0 JTEC 3-H 1 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 2-D | 0 |
| JTEC 2-G 17 JTEC 2-H 0 JTEC 3-B 3 JTEC 3-D 4 JTEC 3-C 0 JTEC 3-F 4 JTEC 3-E 0 JTEC 3-G 2 JTEC 3-H 1 JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 2-F | 1 |
| JTEC 2-H 0 JTEC 3-B 3 JTEC 3-D 4 JTEC 3-C 0 JTEC 3-F 4 JTEC 3-F 0 JTEC 3-B 0 JTEC 3-G 2 JTEC 3-H 1 JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 2-E | 3 |
| JTEC 3-B 3 JTEC 3-D 4 JTEC 3-C 0 JTEC 3-F 4 JTEC 3-E 0 JTEC 3-G 2 JTEC 3-H 1 JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 2-G | 17 |
| JTEC 3-D 4 JTEC 3-C 0 JTEC 3-F 4 JTEC 3-E 0 JTEC 3-G 2 JTEC 3-H 1 JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | ЈТЕС 2-Н | 0 |
| JTEC 3-C 0 JTEC 3-F 4 JTEC 3-E 0 JTEC 3-G 2 JTEC 3-H 1 JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 3-B | 3 |
| JTEC 3-F 4 JTEC 3-E 0 JTEC 3-G 2 JTEC 3-H 1 JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 3-D | 4 |
| JTEC 3-E 0 JTEC 3-G 2 JTEC 3-H 1 JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 3-C | 0 |
| JTEC 3-G 2 JTEC 3-H 1 JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 3-F | 4 |
| JTEC 3-H 1 JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 3-E | 0 |
| JTEC 3-J 2 JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 3-G | 2 |
| JTEC 4-C 0 JTEC 4-D 0 JTEC 4-G 1 | JTEC 3-H | 1 |
| JTEC 4-D 0 JTEC 4-G 1 | JTEC 3-J | 2 |
| JTEC 4-G 1 | JTEC 4-C | 0 |
| | JTEC 4-D | 0 |
| ITFC 4-H | JTEC 4-G | 1 |
| | JTEC 4-H | 2 |

200, 200, 200, 200, 200

| SAMPLE_ID | RESULT |
|-----------|--------|
| JTEC 5-G | 0 |
| JTEC 5-H | 0 |
| JTEC 5-J | 6 |
| JTEC 6-C | 1 |
| JTEC 6-D | 0 |
| ЈТЕС 6-Н | 0 |
| JTEC 6-J | 0 |
| JTEC 7-D | 1 |
| JTEC 8-E | 0 |
| JTEC 8-F | 13 |
| JTEC 6-F | 1 |
| JTEC 6-D | 0 |
| JTEC 6-G | 0 |
| ЈТЕС 6-Е | 0 |
| JTEC 8-E | 0 |
| JTEC 8-D | 3 |
| JTEC 7-H | 0 |
| JTEC 7-E | 3 |
| JTEC 8-G | 2 |
| JTEC 7-G | 0 |
| JTEC 7-F | 2 |

John Twitty Energy Center Temporary Holding Pond Clean Closure Verification


| JTEC 4-K | 9 |
|----------|---|
| JTEC 4-E | 0 |
| JTEC 4-F | 3 |
| JTEC 4-J | 1 |
| JTEC 5-C | 1 |
| JTEC 5-D | 1 |
| JTEC 5-E | 0 |
| JTEC 5-F | 0 |
| | |
| | |

| JTEC 8-C | 1 |
|---------------|----|
| JTEC 7-D | 0 |
| QC01 JTEC 3-B | 3 |
| QC02 JTEC 4-G | 2 |
| QC03 JTEC 5-G | 1 |
| QC04 JTEC 8-F | 10 |
| QC JTEC 7-G | 2 |
| JTEC 7-C | 1 |

Sample IDs starting with QC are laboratory quality control tests.

ATTACHMENT A

JTEC Grid Drawing



ATTACHMENT B

JTEC Test Results



October 4, 2016

Jeff Farah Jacobs Engineering Group Inc. 501 N. Broadway St. Louis, MO 63102-2131

RE:

Jacobs Engineering Group Project - City Utilities of Springfield

RJ Lee Group Project Number AOH1042706-0

Dear Mr. Farah,

The RJ Lee Group, Inc. Monroeville laboratory received 39 samples on September 20, 2016 associated with Jacobs Engineering Group Inc. job number 35DK8201. The samples were logged into RJ Lee Group project number AOH1042706-0 and assigned RJLG sample numbers as indicated in Appendix A.

The samples were received in good condition with all custody seals in place and intact. Attached in Appendix A is the signed sample receipt confirmation form, COC, and sample receipt check list.

If you have any questions or comments regarding the information contained in this report, please feel free to contact us.

These results are submitted pursuant to RI Lee Group's current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. No responsibility or liability is assumed for the manner in which the results are used or interpreted.

Bryan R. Bandli, PhD Principal Investigator

Attachments: Chain of Custody Forms

Mineral Identification Report

Method Blank and Reference Mount Data

Polarized Light Microscopy Images, Bench Sheets,

QC Tabulation (when applicable

WWW.RJLG.COM



1. Description

The James River Power Station (JRPS) site is owned and operated by City Utilities of Springfield, Missouri, and is located south of the city along the James River. The plant consists of five dual-fueled units (coal or natural gas) that are currently permitted to burn only natural gas. Prior to 2016, when the facility was in operation with coal firing, coal combustion residuals (CCR) were sluiced to two onsite temporary holding ponds. CCR was temporarily stored in the ponds until a specific volume was reached. The ponds were then drained and the CCR excavated and placed within the on-site utility waste landfill permitted by Missouri Department of Natural Resources.

City Utilities has closed the temporary holding ponds at JRPS by removing all visible CCR from the temporary holding ponds, and removing the pond liners. This was accomplished in accordance with the construction drawings and specifications under PO 131771. Closure of the west pond and outer embankment was completed (including verification sampling and analysis described below) by February 23, 2017. The east pond closure was completed on June 20, 2017. Final slopes will be contoured and vegetative cover established.

The east and west pond areas were cleaned and verified in the following order: west pond bottom, west pond outer berm, and then the east pond. Clean closure verification followed the procedures outlined in the document titled "Clean Closure Verification of CCR Holding Ponds, April 2016" This plan describes the method of determining the removal of CCR, sample collection and handling, and analysis using Polarized Light Microscopy (PLM) to complete the verification process. This method was used and approved by EPA for clean-up of CCR releases during the TVA Kingston project. A copy of the plan is located in the site Operating Record.

Attachment A includes a diagram depicting the subsoil sampling locations. Grid sample location 1-G, 3-F, 15-F, 17-G, 18-G, 19-G and 19-M were not sampled as these locations fell outside the limits of CCR materials. The values in the table below represent the percentage of CCR material in the subsoil samples. A total of 150 samples were collected, and in most cases single digit percentages of CCR remained in the sample matrix. The results ranged from zero to 33 percent, with the overall average being five percent. Test data information is included in Attachment B. Data Validation Reports are located in Appendix C of this document.

| SAMPLE_ID | RESULT (%) |
|-----------|------------|
| JRPS 4-E | 2 |
| JRPS 5-E | 9 |
| JRPS 6-E | 23 |
| JRPS 7-E | 5 |
| JRPS 8-E | 3 |
| JRPS 4-F | 2 |
| JRPS 5-F | 7 |
| JRPS 6-F | 18 |
| JRPS 7-F | 3 |
| JRPS 8-F | 6 |
| JRPS 9-F | 0 |
| JRPS 10-F | 5 |
| JRPS 11-F | 5 |
| JRPS 12-F | 1 |
| JRPS 13-F | 17 |

| _ |
|----|
| 5 |
| 4 |
| 0 |
| 2 |
| 4 |
| 11 |
| 4 |
| 2 |
| 6 |
| 5 |
| 4 |
| 2 |
| 0 |
| 0 |
| 1 |
| |

| SAMPLE_ID | RESULT (%) |
|-----------|------------|
| JRPS 14-F | 12 |
| JRPS 2-H | 4 |
| JRPS 3-H | 3 |
| JRPS 4-H | 2 |
| JRPS 5-H | 2 |
| JRPS 6-H | 1 |
| JRPS 7-H | 2 |
| JRPS 8-H | 2 |
| JRPS 9-H | 6 |
| JRPS 10-H | 2 |
| JRPS 11-H | 5 |
| JRPS 12-H | 1 |
| JRPS 13-H | 0 |
| JRPS 14-H | 5 |
| JRPS 15-H | 20 |
| JRPS 16-H | 8 |
| JRPS 17-H | 7 |
| JRPS 18-H | 8 |
| JRPS 19-H | 10 |
| JRPS 1-J | 4 |
| JRPS 2-J | 4 |
| JRPS 3-J | 6 |
| JRPS 4-J | 1 |
| JRPS 5-J | 1 |
| JRPS 6-J | 3 |
| JRPS 7-J | 2 |
| JRPS 8-J | 14 |
| JRPS 9-J | 5 |
| JRPS 10-J | 1 |
| JRPS 11-J | 6 |
| JRPS 12-J | 1 |
| JRPS 13-J | 2 |
| JRPS 14-J | 1 |
| JRPS 15-J | 4 |
| JRPS 16-J | 24 |
| JRPS 17-J | 19 |
| JRPS 18-J | 21 |
| JRPS 19-J | 1 |
| JRPS 1-K | 8 |
| JRPS 2-K | 7 |

| SAMPLE_ID | RESULT (%) |
|-----------|------------|
| JRPS 1-H | 3 |
| JRPS 4-K | 9 |
| JRPS 5-K | 13 |
| JRPS 6-K | 11 |
| JRPS 7-K | 14 |
| JRPS 8-K | 8 |
| JRPS 9-K | 3 |
| JRPS 10-K | 4 |
| JRPS 11-K | 11 |
| JRPS 12-K | 0 |
| JRPS 13-K | 4 |
| JRPS 14-K | 5 |
| JRPS 15-K | 8 |
| JRPS 16-K | 1 |
| JRPS 17-K | 1 |
| JRPS 18-K | 4 |
| JRPS 19-K | 4 |
| JRPS 1-L | 5 |
| JRPS 2-L | 13 |
| JRPS 3-L | 6 |
| JRPS 4-L | 3 |
| JRPS 5-L | 1 |
| JRPS 6-L | 11 |
| JRPS 7-L | 3 |
| JRPS 8-L | 2 |
| JRPS 9-L | 14 |
| JRPS 10-L | 9 |
| JRPS 11-L | 9 |
| JRPS 12-L | 2 |
| JRPS 13-L | 8 |
| JRPS 14-L | 11 |
| JRPS 15-L | 3 |
| JRPS 16-L | 1 |
| JRPS 17-L | 0 |
| JRPS 18-L | 8 |
| JRPS 19-L | 3 |
| JRPS 2-M | 11 |
| JRPS 3-M | 4 |
| JRPS 4-M | 25 |
| JRPS 5-M | 4 |


| SAMPLE_ID | RESULT (%) |
|-----------|------------|
| JRPS 3-K | 11 |
| JRPS-7-M | 2 |
| JRPS-8-M | 0 |
| JRPS-9-M | 1 |
| JRPS-10-M | 5 |
| JRPS-11-M | 2 |
| JRPS-12-M | 2 |
| JRPS-13-M | 0 |
| JRPS-14-M | 2 |
| JRPS-15-M | 0 |
| JRPS-16-M | 1 |
| JRPS-17-M | 2 |
| JRPS 18-M | 0 |
| JRPS 4-N | 11 |
| JRPS 5-N | 21 |
| JRPS 6-N | 33 |
| JRPS-7-N | 0 |
| JRPS-8-N | 1 |
| JRPS-9-N | 2 |
| JRPS-10-N | 1 |
| JRPS-11-N | 3 |
| JRPS-12-N | 4 |
| JRPS-13-N | 1 |


| SAMPLE_ID | RESULT (%) |
|----------------|------------|
| JRPS-6-M | 6 |
| JRPS-14-N | 2 |
| JRPS-15-N | 1 |
| JRPS-16-N | 0 |
| JRPS 17-N | 5 |
| JRPS 18-N | 4 |
| JRPS 6-O | 0 |
| JRPS 7-0 | 4 |
| JRPS 8-O | 0 |
| JRPS 9-O | 13 |
| JRPS 10-O | 5 |
| JRPS 11 - O | 6 |
| JRPS 12-O | 5 |
| JRPS 13-O | 11 |
| JRPS 14-0 | 9 |
| JRPS 15-O | 15 |
| JRPS 16-O | 5 |
| QC01 JRPS 1-H | 1 |
| QC02 JRPS 4-L | 1 |
| QC03 JRPS 14-L | 2 |
| QC04 JRPS 10-M | 3 |
| QC05 JRPS 9-N | 2 |
| QC _ JRPS 8-O | 0 |

Sample IDs starting with QC are laboratory quality control tests.

ATTACHMENT A

JRPS Grid Drawing





ATTACHMENT B

JRPS Test Results Level IV Results



November 15, 2016

Jeff Farah Jacobs Engineering Group Inc. 501 N. Broadway St. Louis, MO 63102-2131

RE:

Jacobs Engineering Group Project - City Utilities of Springfield

RJ Lee Group Project Number AOH1042706-4

Dear Mr. Farah,

The RJ Lee Group, Inc. Monroeville laboratory received 49 samples on November 2, 2016 associated with Jacobs Engineering Group Inc. job number 35DK8201. The samples were logged into RJ Lee Group project number AOH1042706-4 and assigned RJLG sample numbers as indicated in Appendix A.

The samples were received in good condition with all custody seals in place and intact. Attached in Appendix A is the signed sample receipt confirmation form, COC, and sample receipt check list.

If you have any questions or comments regarding the information contained in this report, please feel free to contact us.

These results are submitted pursuant to RJ Lee Group's current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. No responsibility or liability is assumed for the manner in which the results are used or interpreted.

Sincerely,

Bryan R. Bandli, PhD Principal Investigator

Attachments: Chain of Custody Forms

Mineral Identification Report

Method Blank and Reference Mount Data

Polarized Light Microscopy Images, Bench Sheets,

QC Tabulation (when applicable)